FACILITIES

Richmond Highlands Community Center 16554 Fremont Avenue North

Improvements since 2003

- Refinished floors
- Purchased lockers
- Painted walls
- New appliances
- Building maintenance and repairs

Draft Considerations

- Renovate restrooms behind stage
- Repair/replace interior surfaces and systems including:
 - HVAC
 - Plumbing and electrical
 - Flooring and furnishings
- New interior restrooms
- Expand stage and add storage
- Add classroom space
- Remodel kitchen and storage area
- Raise gym ceiling
- Install retractable basketball hoops